

ENVIRONMENTAL PROTECTION  
AGENCY

HESS OIL VIRGIN ISLANDS CORP.

1994 AUG -4 AM 11: 35

AWM-HAZ WASTE FAC. BRANCH

15A

CA94-07/27/94

REPLY TO:  
KINGSHILL, P. O. BOX 127  
ST. CROIX, U. S. VIRGIN ISLANDS  
00851-0127

July 27, 1994

CERTIFIED MAIL P 021 976 568  
RETURN RECEIPT REQUESTED

Mr. Tim Gordon  
NJ/Caribbean Corrective Action Section  
Hazardous Waste Management Facilities Branch  
U.S. Environmental Protection Agency  
26 Federal Plaza  
New York, N.Y. 10278


Dear Mr. Gordon:

HOVIC is submitting the attached updated Oily Water Conveyance and Tank Testing map in compliance with the request of the July 7, 1994 letter from Mr. Andrew Bellina.

The map format has been revised to reflect the near completion of the initial internal floor inspections and repairs and to focus on the annual in-service static head testing progress. The oily water conveyance portion of the map has also been revised to more simply show the status of line testing, retesting and repair.

If you have any additional questions regarding this submittal, please contact the undersigned at (809)778-4251.

Sincerely,



Joel W. Stephens  
Environmental Manager

JWS/egt

Attachment